
Solutions for Excessive Fifth Wheel Slack

Troubleshooting Flow Chart 6000/7000 Series



A Marmon Highway Technologies®/Berkshire Hathaway Company

OM @FifthWheelParts @ @FontaineParts f ©2017 Fontaine Fifth Wheel • LT-226 • July 2017 R4